



Republic of the Philippines
LEYTE METROPOLITAN WATER DISTRICT
 A DOH ACCREDITED WATER TESTING LABORATORY
 Accreditation No.: 13-001-08-LW-2
 Rapid Filtration Plant, Brgy. Hibunawon, Jaro, Leyte
 Telefax No. (053) 332-7465/332-7424

BACTERIOLOGICAL TEST RESULT FOR WATER

Name of Client: **CATBALOGAN WATER DISTRICT** Submitted by: ZALDY A. MAHINAY
 Address : Brgy. 4, Allen Avenue, Catbalogan, City Contact No.:

Lab. No.	Sample Source and Address	Date and Time of:			Result of Analysis			Remarks
		Collection	Receipt	Examination	Total (MPN)	Fecal (MPN)	HPC (CFU/ML)	
		March 20, 2014						
14-220	Faucet, Brgy. 1, Catbalogan, City	6:56 AM	8:00 PM	9:00 PM	<1.1	<1.1	3	PASSED
14-221	Faucet, Brgy. 8, Catbalogan, City	7:07 AM	8:00 PM	9:05 PM	<1.1	<1.1	1	PASSED
14-222	Faucet, Brgy. Buno-Anan, Catbalogan, City	7:18 AM	8:00 PM	9:10 PM	<1.1	<1.1	15	PASSED
14-223	Faucet, Brgy. Guindapunan, Catbalogan, City	7:30 AM	8:00 PM	9:15 PM	<1.1	<1.1	2	PASSED

Remarks: 1. The results given in this report were obtained at the time of the analysis and refer only to the particular sample submitted.
 2. This result shall not be reproduced unless in full.

Philippine National Standards for Drinking Water (PNSDW)
 MPN = Most Probable Number
 CFU = Colony Forming Unit

MPN/100 ml. Total Coliform =
 MPN/100 ml. Fecal Coliform =
 Heterotrophic Plate Count =

Public Water Supplies
 Less than 1.1 or 0
 Less than 1.1 or 0
 Less than 500 CFU/ml

Analyst: *Katherine S. Zabala*
KATHERINE S. ZABALA, RMT
 Medical Technologist

Certified Correct:
Rosalinda A. Dumagosa
ROSALINDA A. DUMAGOSA
 Quality Control/Assurance Officer

Noted: *Cynthia L. Terrado*
CYNTHIA L. TERRADO
 OIC, Div. Mgr., Quality Control